



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
RUSHLEY CLOSE	Side of 89 Rushley Rd	TR: Felling	F/W damaged and potential 3rd party wall damage	Prunus padus	Plant in existing pit on Rushley Close at side of 89 Rushley Road	Malus 'Rudolph'
RUSHLEY CLOSE	O/S 11	TR: Felling	F/W uplifted and potential 3rd party wall damage	Prunus Kanzan	Plant in existing pit o/s 11 (same position as felled tree)	Malus 'Rudolph'
RUSHLEY CLOSE	O/S 12	TR: Felling	Kerb displaced and f/w mounded	Sorbus intermedia	Plant in existing pit o/s 12 (same position as felled tree)	Malus 'Rudolph'